### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020257 Address: 333 Burma Road **Date Inspected:** 27-Jan-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Oiu Wei **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG COMPONENT** 

## **Summary of Items Observed:**

On this day Caltrans OSM Quality Assurance (QA) Inspector Subhasis Bera was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China. QA Inspector observed and/or found the following:

In process Inspection

Bay#14

This QA Inspector observed the following work in progress:

SMAW in the 3G position for the OBG Segment 13CW weld No.DP3148-001-247. The welder is identified as #037840. ZPMC QC is identified as Mr. Zhang Lin. The welding variables recorded by QC appear to comply with WPS-B-P-2213-Tc-U4b-FCM-1.

SMAW in the 3G position for the OBG Segment 13CW UT repair weld No.SEG3015D-311. The welder is identified as #037932. ZPMC QC is identified as Mr. Zhang Lin. The welding variables recorded by QC appear to comply with WPS-345-SMAW-3G(3F)-FCM-REPAIR-1. The weld repair report is identified as WR20190.

FCAW in the 2F position for the OBG Segment 14W weld No.SEG3020AZ-005/006. The welder is identified as #066695. ZPMC QC is identified as Mr. Zhang Lin. The welding variables recorded by QC appear to comply with WPS-B-T-2132-ESAB.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SMAW in the 2G position for the OBG Segment 14W ,UT repair weld No.SEG3020D-052. The welder is identified as #066038. ABF QC is identified as Mr. Yan Bao Jia. The welding variables recorded by QC appear to comply with WPS-345-SMAW-2G(2F)-FCM-REPAIR-1. The weld repair report is identified as CWR2734.

SMAW in the 2G position for the OBG Segment 14W, UT repair weld No.SEG3020E-056. The welder is identified as #066398. ABF QC is identified as Mr. Yan Bao Jia. The welding variables recorded by QC appear to comply with WPS-345-SMAW-2G(2F)-FCM-REPAIR-1. The weld repair report is identified as CWR2734.

SMAW in the 3G position for the OBG Segment 14W weld No.DP3171-001-189. The welder is identified as #069493. ABF QC is identified as Mr. Shen Jian. The welding variables recorded by QC appear to comply with WPS-B-P-2213-Tc-U4b-FCM-1.

FCAW in the 2G position for the OBG Segment 14W weld No.DP3171-001-022. The welder is identified as #066236. ABF QC is identified as Mr. Shen Jian. The welding variables recorded by QC appear to comply with WPS-B-T-2232-ESAB.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





#### **Summary of Conversations:**

No relevant conversations

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Bera, Subhasis	Quality Assurance Inspector
Reviewed By:	Dsouza, Christopher	QA Reviewer